



CLEANER CLOTH

ABSORBENT, LINT-FREE CLOTH



PRODUCT DESCRIPTION

Absorbent, lint-free cloth.

FIELD OF APPLICATION

For cleaning and degreasing piping, sleeves and fittings made of PVC, PVC-C, ABS, PE, PP, PVDF and PB prior to joining or welding. Use in combination with the Griffon Cleaner or PE Cleaner. Also suitable for removing uncured adhesive residue.

PROPERTIES

- Absorbent
- Lint-Free
- 23 x 41 cm

APPLICATION

Directions for use:

1. Moisten cloth with (PE) Cleaner.
2. Clean and degrease surfaces.
3. Remove any emerging condensation with a clean, dry cloth and allow surfaces to dry properly.

Our advice is based on extensive research and practical experience. However, in view of the large variety of materials and the conditions under which our products are applied, we assume no responsibility for the results obtained and/or any damage caused by the use of the product. Nevertheless, our Service Department is always at your disposal for any advice needed.